

NOZZLE RATING CHART

Orifice
Size

0°	400 PSI	500 PSI	600 PSI	700 PSI	800 PSI	1000 PSI	1250 PSI	1500 PSI	2000 PSI	2500 PSI	3000 PSI	4000 PSI	5000 PSI	6000 PSI	7000 PSI
03.0	0.9	1.0	1.1	1.2	1.3	1.5	1.6	1.8	2.1	2.3	2.5	3.0	3.3	3.6	3.9
03.5	1.1	1.2	1.4	1.5	1.6	1.8	2.0	2.1	2.5	2.8	3.0	3.5	3.9	4.3	4.6
04.0	1.2	1.4	1.5	1.7	1.8	2.0	2.2	2.4	2.8	3.1	3.5	4.0	4.5	4.9	5.3
04.5	1.4	1.5	1.7	1.8	2.0	2.2	2.5	2.7	3.1	3.5	3.8	4.5	5.0	5.5	5.9
05.0	1.5	1.8	1.9	2.1	2.2	2.5	2.7	3.1	3.5	3.9	4.3	5.0	5.6	6.1	6.6
05.5	1.7	1.9	2.1	2.3	2.5	2.8	3.0	3.4	3.9	4.3	4.8	5.5	6.2	6.7	7.3
06.0	1.8	2.1	2.3	2.5	2.7	3.0	3.3	3.7	4.2	4.7	5.2	6.0	6.7	7.3	7.9
06.5	2.0	2.3	2.5	2.7	2.9	3.3	3.6	4.0	4.6	5.1	5.6	6.5	7.3	8.0	8.6
07.0	2.2	2.5	2.7	2.9	3.1	3.5	3.9	4.3	4.9	5.5	6.1	7.0	7.8	8.6	9.3
07.5	2.3	2.7	2.9	3.1	3.4	3.8	4.1	4.6	5.3	5.9	6.5	7.5	8.4	9.2	9.9
08.0	2.5	2.8	3.1	3.3	3.6	4.0	4.4	4.9	5.7	6.3	6.9	8.0	8.9	9.8	10.6
08.5	2.6	3.0	3.3	3.6	3.8	4.3	4.7	5.2	6.0	6.7	7.4	8.5	9.5	10.4	11.2
09.0	2.8	3.2	3.5	3.8	4.0	4.5	5.0	5.5	6.4	7.1	7.8	9.0	10.1	11.0	11.9
10.0	3.1	3.5	3.9	4.2	4.5	5.0	5.5	6.1	7.1	7.9	8.7	10.0	11.2	12.2	13.2
12.5	3.9	4.4	4.8	5.2	5.6	6.3	6.9	7.7	8.8	9.8	10.8	12.5	14.0	15.3	16.5
15.0	4.7	5.3	5.8	6.3	6.7	7.5	8.3	9.2	10.6	11.8	12.9	15.0	16.8	18.4	19.8

Progressive Pressure Systems

1248 East Newport Road

Lititz, PA 17543

Phone: (717) 626-5511 Fax: (717) 626-5098